

© **Liofilchem**® Product Catalogue 2014

Organic residue detection on surfaces		
Description	Packaging	Ref.
CLEAN TEST	50 test	86001
Swab for detecting protein, fat and sugar residues for the hygiene control of surfaces.	3 test	86001/3